



GENERAL CONSTRUCTION NOTE:

1. STANDARD 5/8" SQUARE NUTS ISSUED WITH DA BOLTS, MH BOLTS AND STEEL INSULATOR PINS SHOULD BE USED FOR LOCK (JAM) NUTS.
2. DISCARD SQUARE WASHER AND LOCK (MF) NUT ISSUED WITH STEEL INSULATOR PIN, USE ISSUED NUT WASHER IN PLACE OF SQUARE WASHER.

ENGINEERING NOTE:

1. LIGHTNING ARRESTOR POSITION WHEN USED WITHOUT TRANSFORMER (OH-30002)
2. LIGHTNING ARRESTOR AND GROUND ROD TO BE SPECIFIED BY ENGINEER

A	8' CROSSARM
B	10' CROSSARM

TITLE:

THREE PHASE DEAD  
END ON FIBER ARM

**GARLAND**  
POWER & LIGHT

DRAWN BY: GL	DATE: 8/3/04	APPROVED BY: CP
REVISED BY:	DATE:	APPROVED BY:

STANDARD NO.:

OH-1655

**CONSTRUCTION STANDARD NO. : OH-1655A****TITLE: THREE PHASE DEADEND 8' FIBERGLASS CROSSARM**

REV. DATE: 10/1/2004

PIC. #	DESCRIPTION	IBM NO.	QTY.
1	CROSSARM, 8' FIBERGLASS DEADEND (GRAY IN COLOR)	285-22-25350	1
2	NUT 5/8" OVAL EYE	285-08-56640	1
3	INSULATOR DEAD END 3.5" X 12-1/2" LENGTH CHANCE #C654-3015	286-42-26020	3
4	CLAMP DEADEND STRAIGHT LINE .464" TO .860"	285-13-16390	4
5	BOLT DOUBLE ARMING 5/8" X 14"	285-08-21552	1
6	BOLT MACHINE 3/4" X 12" W/NUT	285-08-10812	2
7	NUT 3/4" OVAL EYE	285-08-56642	1
8	NUT WASHER 5/8" THREAD JOSLYN	285-08-14674	2
9	NUT WASHER 3/4"	285-08-74676	3

**CONSTRUCTION STANDARD NO. : OH-1655B****TITLE: THREE PHASE DEADEND 10' FIBERGLASS CROSSARM**

REV. DATE: 10/1/2004

PIC. #	DESCRIPTION	IBM NO.	QTY.
1	CROSSARM, 10' FIBERGLASS DDE HEAVY DUTY LEWTEX	285-22-25400	1
2	NUT 5/8" OVAL EYE	285-08-56640	1
3	INSULATOR DEAD END 3.5" X 12-1/2" LENGTH CHANCE #C654-3015	286-42-26020	3
4	CLAMP DEADEND STRAIGHT LINE .464" TO .860"	285-13-16390	4
5	BOLT DOUBLE ARMING 5/8" X 14"	285-08-21552	1
6	BOLT MACHINE 3/4" X 12" W/NUT	285-08-10812	2
7	NUT 3/4" OVAL EYE	285-08-56642	1
8	NUT WASHER 5/8" THREAD JOSLYN	285-08-14674	2
9	NUT WASHER 3/4"	285-08-74676	3